

Table of Contents

<u>3.</u>	<u>Maintenance</u>	3.1
3.1	Measuring Instruments and Auxiliary Equipment Required	3.1
3.2	Performance Check	3.1
3.2.1	Checking the Accuracy of the Level Measurement	3.1
3.2.1.1	Checking the Level Indication in the 20-dB Operating Level Range	3.1
3.2.1.2	Checking the Level Indication in the 40-dB / 60-dB Operating Level Range	3.3
3.2.1.3	Checking the Level Indication in the CISPR (Publication 3) Mode of Indication	3.4
3.2.1.4	Checking the Level Indication in the CISPR (Publication 1) Mode of Indication	3.5
3.2.1.5	Checking the Generator Output	3.6
3.2.1.5.1	Checking the Generator Output in the TWOPORT Mode	3.6
3.2.1.5.2	Checking the Generator Output in the REM. FREQ. Mode	3.6
3.2.1.6	Checking the Attenuator	3.6
3.2.1.7	Checking the IF Level Switch	3.7
3.2.2	Checking the Analog Readouts	3.7
3.2.2.1	Checking the Analog Level Indication	3.7
3.2.2.2	Checking the Analog Frequency Offset Indication	3.8
3.2.3	Checking the Special Functions	3.8
3.2.3.1	Checking the Modulation Depth Measurements	3.8
3.2.3.2	Checking the Frequency Offset Measurement	3.9
3.2.3.3	Checking the Deviation Measurements	3.10
3.2.4	Checking the Frequency Accuracy	3.10
3.2.5	Checking the IF Bandwidths	3.11
3.2.6	Checking the Noise Figure	3.11
3.2.7	Checking the Input Reflection Coefficient	3.12
3.2.8	Checking the Oscillator Reradiation at the RF Input	3.13
3.2.9	Checking the 75-MHz IF Rejection	3.13

3.2.10	Checking the Image Frequency Rejection	3.13
3.2.11	2nd Order Harmonic Distortion (a_{K2})	3.14
3.2.12	2nd and 3rd Order Intermodulation Rejection	3.15
3.2.13	Checking the Crossmodulation	3.16
3.2.14	Checking the RF Leakage	3.17
3.2.15	Checking the Outputs	3.17
3.2.15.1	30-kHz IF Output	3.17
3.2.15.2	75-MHz IF Output	3.18
3.2.15.3	AM Demodulator Output	3.18
3.2.15.4	FM Demodulator Output	3.18
3.2.15.5	Level Output AV./ PEAK	3.19
3.2.15.6	Level Output CISPR	3.19
3.2.15.7	Frequency Offset Output	3.19
3.2.16	Check of Operation Using External Reference	3.19
3.2.17	Checking the Recorder Output	3.20
3.2.18	Checking the IEC-bus Output	3.20
3.3	Electrical Maintenance	3.20
3.4	Mechanical Maintenance	3.21
3.5	Storage	3.21

<u>4.</u>	<u>Circuit Description</u>	4.1
4.1	Electrical Function of the Individual Boards	4.1
4.1.1	Display Unit (Y1)	4.1
4.1.2	Computer Board (Y2)	4.3
4.1.3	Analog Circuit (Y3)	4.6
4.1.3.1	General	4.6
4.1.3.2	Signal Path for Level Measurement	4.7
4.1.3.3	Signal Path for Frequency Offset Measurement	4.7
4.2.3.4	AF Amplifier	4.8
4.1.4	Synthesizer 2 (Y4)	4.8
4.1.4.1	60-MHz Reference Oscillator	4.9
4.1.4.2	Interpolation Oscillator	4.10
4.1.4.3	Mixer Oscillator	4.10
4.1.5	Synthesizer 1 (Y5)	4.11
4.1.6	RF Preselection	4.14
4.1.6.1	Filter Control (Y6)	4.14
4.1.6.2	Filter 1 (Y7)	4.16
4.1.6.3	Filter 2 (Y8)	4.17
4.1.7	1st and 2nd Mixers (Y9)	4.17
4.1.8	Calibration Generator (Y10)	4.18
4.1.8.1	Sinewave Calibration with AV., PEAK Indication	4.19
4.1.8.2	Pulse Calibration (CISPR 3: $f < 150$ kHz; CISPR 1: $f \geq 150$ kHz)	4.20
4.1.9	3rd Mixer (Y11)	4.20
4.1.10	Indication and AF Demodulation (Y12)	4.21
4.1.10.1	IC Switches	4.24
4.1.10.2	Indication Section	4.26
4.1.10.2.1	Logarithmic Amplifier	4.26
4.1.10.2.2	Indication Demodulation	4.27
4.1.10.2.2.1	CISPR Meter Amplifier	4.27
4.1.10.2.2.2	Meter Amplifier for Average- and Peak-value Indication ...	4.28
4.1.10.2.3	Indication Outputs	4.28
4.1.10.2.3.1	Meter Output (ST1/a2)	4.28
4.1.10.2.3.2	Recorder Output (ST1/a6)	4.29
4.1.10.3	AF Demodulation	4.29
4.1.10.3.1	FM Demodulation	4.29
4.1.10.3.2	AM, SSB and Telegraphy Demodulation	4.30

4.1.10.3.2.1	AM Demodulation	4.31
4.1.10.3.2.2	Demodulation of A0, A1, USB, LSB	4.32
4.1.10.4	4th Oscillator	4.33
4.1.10.4.1	Oscillator	4.34
4.1.10.4.2	Adjustable Divider	4.34
4.1.10.4.3	Phase Comparator and Synchronization Indication	4.36
4.1.10.4.4	Supply Voltage Switch of the 4th Oscillator	4.37
4.1.10.4.5	30-kHz Output (ST5)	4.37
4.1.11	Attenuator Control (Y13)	4.38
4.1.12	Power Supply	4.39
4.1.12.1	Functional Description	4.39
4.1.12.2	Rectifier Board	4.39
4.1.12.3	Switching Power Supply	4.41
4.1.12.3.1	Regulators +5 V and +12 V	4.41
4.1.12.3.2	Reverse Converter	4.42
4.1.12.4	Analog Power Supply	4.42.1
4.1.12.4.1	+15-V Supply	4.42.1
4.1.12.4.2	+8-V Reference Voltage Sources	4.42.1
4.1.12.4.3	+10-V/0.8-A Supply	4.42.1
4.1.12.4.4	-10-V/0.8-A Supply	4.42.2
4.1.12.4.5	+20-V/0.4-A (25-V/0.04-A) Supply	4.42.2
4.1.12.4.6	+30-V/0.06-A Supply	4.42.2
4.1.12.5	Voltage Monitoring	4.42.2
4.1.12.5.1	Input Undervoltage	4.42.3
4.1.12.5.2	Internal Undervoltage	4.42.3
4.1.12.5.3	Window Comparators	4.42.4
4.1.12.5.4	Startup and RESET	4.42.4
4.1.13	Recorder Control	4.43
4.1.13.1	IEC-625 Bus	4.43
4.1.13.2	Recorder Outputs	4.44
4.1.14	Attenuator (Y16)	4.45
4.1.15	Motherboard	4.46
4.2	Mechanical Construction	4.46
4.3	Arrangement of the Boards	4.46
4.4	Location of Trimming Components	4.48

<u>5.</u>	<u>Repair</u>	5.1
5.1	Measuring Instruments and Auxiliary Equipment Required	...	5.1
5.2	Failure Location	5.1
5.2.1	No Response at Switch-on or Readout Makes no Sense	5.1
5.2.2	Receiver Fails to Self-calibrate	5.2
5.2.3	Receiver Self-calibrates but Indication Incorrect in AV. Mode	5.4
5.2.4	Receiver Self-calibrates but Indication Incorrect in CISPR Mode	5.4
5.2.5	Error Messages of ESH3 and Possible Causes	5.4.1
5.3	Adjustment and Performance Check of the ESH 3	5.4.8
5.3.1	Adjustment of the Various Boards	5.4.8
5.3.1.1	Display Unit	5.4.8
5.3.1.1.1	Supply Voltages	5.5
5.3.1.1.2	Frequency Indication	5.5
5.3.1.1.3	Analog Level Indication	5.5
5.3.1.1.4	Analog Offset Indication	5.5
5.3.1.1.5	Signature Analysis	5.5
5.3.1.1.6	Keyboard and Display Interface	5.6
5.3.1.1.7	Difference Current Sink	5.6
5.3.1.2	Computer Board	5.7
5.3.1.2.1	Supply Voltages	5.7
5.3.1.2.2	Signature Analysis	5.7
5.3.1.2.2.1	Free-running Signature Analysis	5.7
5.3.1.2.2.2	Software-driven Signature Analysis	5.8
5.3.1.2.3	A/D Converter	5.9
5.3.1.3	Analog Circuit Board	5.9
5.3.1.3.1	Supply Voltages	5.9
5.3.1.3.2	General	5.10
5.3.1.3.3	Analog Level Path	5.10
5.3.1.3.3.1	Level Calibration	5.10
5.3.1.3.3.2	Programmable Amplifiers B2/I, B2/II	5.10
5.3.1.3.3.3	Adjusting the Logarithmic Converter	5.11
5.3.1.3.3.4	Max. Level and Min. Level	5.11
5.3.1.3.4	Frequency Offset Signal Path	5.11
5.3.1.3.4.1	Offset Calibration	5.11
5.3.1.3.4.2	Peak-value Rectification	5.12
5.3.1.3.4.3	Frequency Correction Voltage	5.12

5.3.1.3.4.4	AF Amplifier	5.13
5.3.1.4	Synthesizer 2 (Y4)	5.13
5.3.1.4.1	Supply Voltages	5.13
5.3.1.4.2	Reference	5.13
5.3.1.4.3	50-to-51-MHz Oscillator	5.14
5.3.1.4.4	66-MHz Oscillator	5.16
5.3.1.5	Synthesizer 1 (Y5)	5.18
5.3.1.5.1	Supply Voltages	5.18
5.3.1.5.2	Adjustment of 75/85/95/105-MHz Oscillators	5.18
5.3.1.5.3	Adjustment of Output Level	5.19
5.3.1.5.4	Adjustment of 65-MHz Amplifier	5.19
5.3.1.5.5	Adjustment of 10-to-40-MHz Amplifier	5.20
5.3.1.5.6	Checking the Synchronization Indication	5.20
5.3.1.5.7	Checking the Synchronization	5.20
5.3.1.5.8	Checking the Sideband Noise	5.20
5.3.1.6	Filter Control (Y6)	5.21
5.3.1.6.1	Supply Voltages	5.21
5.3.1.6.2	Checking the Digital Section	5.22
5.3.1.6.3	Checking the Analog Section (Pre-adjustment)	5.22
5.3.1.7	Filter 1 (Y7)	5.23
5.3.1.8	Filter 2 (Y8)	5.24
5.3.1.8.1	Supply Voltages	5.24
5.3.1.8.2	Adjustment of Filter 15	5.25
5.3.1.8.3	Adjustment of Filter 16	5.25
5.3.1.9	Mixers 1 and 2 (Y9)	5.25
5.3.1.9.1	Supply Voltages	5.25
5.3.1.9.2	Adjustment of Input Low-pass Filter	5.25
5.3.1.9.3	Adjustment of 75-MHz Amplifier	5.26
5.3.1.9.4	Adjustment of Diplexer of 2nd Mixer	5.26
5.3.1.9.5	Adjustment of 9-MHz Amplifier	5.26
5.3.1.9.6	500-Hz Bandwidth	5.26
5.3.1.9.7	2.4-kHz Bandwidth	5.26
5.3.1.9.8	10-kHz Bandwidth	5.27
5.3.1.9.9	Adjustment of Overload Detection	5.27
5.3.1.9.9.1	Overload Detection 2	5.27
5.3.1.9.9.2	Overload Detection 1	5.27
5.3.1.9.9.3	Checking the Level at ST4	5.27
5.3.1.9.9.4	Checking the Level at ST6	5.27

5.3.1.10	Calibration Generator (Y10)	5.28
5.3.1.10.1	Supply Voltages	5.28
5.3.1.10.2	Adjustment of Sinewave Generator	5.28
5.3.1.10.3	Adjustment of Temperature Compensation of Sinewave Generator	5.29
5.3.1.10.4	Checking the CISPR 3 or CISPR 1 Pulse Generator	5.30
5.3.1.11	Mixer 3 (Y11)	5.32
5.3.1.11.1	Supply Voltages	5.32
5.3.1.11.2	Adjustment of 8.97-MHz Oscillator	5.32
5.3.1.11.3	Adjustment of Basic Gain between ST2 and ST5	5.32
5.3.1.11.4	Checking the Noise Filter Bandwidth	5.33
5.3.1.11.5	Checking the Calibration Gain Control Range	5.33
5.3.1.11.6	Checking the IF Attenuation Steps	5.34
5.3.1.11.7	Checking the IF Output Amplifier	5.34
5.3.1.11.8	Checking the 200-Hz Bandwidth and Adjustment of Gain	5.35
5.3.1.11.9	Checking the Overload Detection	5.35
5.3.1.12	Indication and AF Demodulation Board (Y12)	5.35
5.3.1.12.1	Supply Voltages	5.35
5.3.1.12.2	Adjustment of Indication Section	5.36
5.3.1.12.3	AF Demodulation	5.38
5.3.1.13	Performance Check of the Indication and AF Demodulation Board Y12	5.40
5.3.1.13.1	Indication Demodulation	5.40
5.3.1.13.2	AF Demodulation	5.41
5.3.1.14	Attenuator Control (Y13)	5.42
5.3.1.14.1	Supply Voltages	5.42
5.3.1.15	Power Supply	5.44
5.3.1.15.1	Access to Circuits	5.44
5.3.1.15.2	Adjustment of Reference Voltages	5.45
5.3.1.15.3	Test Points of Analog Power Supply	5.46
5.3.1.15.4	Check of Output Currents	5.46
5.3.1.15.5	Check of Monitoring Circuit	5.47
5.3.1.15.6	Notes on Troubleshooting	5.49
5.3.1.16	Checking the Recorder Control Board	5.51
5.3.1.16.1	IEC-bus Section	5.51
5.3.1.16.2	Checking the Demultiplexer	5.51

5.3.1.16.3	Checking the External Reference Switchover	5.52
5.3.1.17	Motherboard (Y18)	5.52
5.3.1.18	RF Attenuator (Y16)	5.52
5.3.2	Overall Adjustment	5.52 b
5.3.2.1	Checking the Supply Voltages	5.52 b
5.3.2.2	Checking the Gain of Mixers 1 + 2 (Y9) and Mixer 3 (Y11) .	5.52 b
5.3.2.3	Checking for Equal Gain with the Various Bandwidths	5.53
5.3.2.4	Adjusting Filters 15 and 16 (Y8)	5.53
5.3.2.5	Checking the Reference Frequency	5.54
5.3.2.6	Adjustment of Calibration	5.54
5.3.2.7	Checking the CISPR 3 Weighting Circuit	5.55
5.3.2.8	Pulse Calibration (CISPR 1) over Frequency Range > 150 kHz	5.55
5.3.2.9	Checking the CISPR 1 Weighting Circuit	5.56
5.3.3	Final Check of the Receiver Performance Data	5.56
5.4	Electrical Repair	5.57
5.5	Mechanical Repair.....	5.57
5.6	Spare Parts	5.57